

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - GLO survey by Wells Lake, Deputy Surveyor, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8561)

-----  
Set ¼ sec. post, from which  
A Maple 5" dia., bears S.10°W., 18 lks.  
A Fir 10" dia., bears N.5°E., 8 lks.

George J. Wenderoth, Deputy - June 1957 - C.S. File 45/154 and M 5-28

-----  
One inch harrow tooth:  
20" Cedar S.61°E., 81.3 ft.  
14" Cedar S.10°30'E., 115.1 ft.

Cor. OK, Aug. 1967, DCSO, John Powell

Survey by William Ruppert, L.S. #866 - For: James Booth - July 1979 - M 78-29 A&B

-----  
CONDITION REPORT ONLY  
Found - 3/4" Iron rod, N.0°23'11"W., 113.30 ft.  
22" Cedar, good scars, S.61°35'E., 81.5 ft.  
16" Cedar good scars, S.11°15'E., 115.65 ft.  
Harrow tooth not found, per M 35-79

BLM resurvey by Virgil L. Stanger, Cadastral Surveyor, under Group #1145, surveyed May/Aug. 1983 - (DCSO records Vol. 47 Page(s) 17879-80)

-----  
The ¼ sec. cor., perpetuated by person(s) unknown, from original evidence no longer in existence, and subsequently perpetuated and recorded by Wenderoth in 1953, and rehabilitated and recorded by the County in 1979. Mr. Donald W. Brady, a resident of the area for many years, furnished a signed statement, attached to and made a portion of these field notes, attesting to the corner position. The corner is monumented with a harrow tooth, 1" square, the top buried 6" below ground, from which bearing trees mkd. by Wenderoth:

A Cedar 25" dia., bears S.60½°E., 121½ lks. dist., with healed blaze.  
A Cedar 17" dia., bears S.9 3/4°E., 175 lks. dist., with healed blaze.

and a property corner established by Wenderoth in 1968, and rehabilitated and recorded by the County as a reference monument in 1979:

An iron rod 3/4" dia., the top buried 2" below ground, bears N.0°52'E., 172 ft. dist. (Cont. Next Page)

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set an iron post, 28" long, 2½" dia., 40" in the ground, the top 12" below surface of the ground, directly over harrow tooth, with brass cap mkd:

T 32 S R 5 W

¼ S 14  
S 23  
1983

from which a new bearing tree

A Fir 28" dia., bears N.4 3/4°W., 330 lks. dist., mkd. ¼ S14 BT.

Corner is located at intersection of dirt roads, both 25 lks. wide, bearing N., S., and W.

Fd. as per record 11/2023 R Brown - M178-77