

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under contract # 420 survey dated Sept. 16 1881 (DCSO records Vol. 20 Page(s) 8696-97)

Set a Chinquapin post 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 5, 6, 7 and 8, marked T32S R6W S5 on NE.; S8 on SE.; S7 on SW.; and S6 on NW. faces, with 5 notches on S. and E. edges, from which
A Fir 36" dia., bears N.85°E., 30 lks. dist., marked T32S R6W S5 BT.
A Fir 30" dia., bears S.85°E., 37 lks. dist., marked T32S R6W S8 BT.
A Fir 36" dia., bears S.70°W., 32 lks. dist., marked T32S R6W S7 BT.
A Fir 34" dia., bears N.12°W., 88 lks. dist., marked T32S R6W S6 BT.

Douglas Co. Surveyors Office - John M. Powell, Joe Brady, crew - Sept. 24, 1965 - C.S. File 49/91-14

Found - Orig. 36" Fir now 50", N.85°E., 19.8 ft., bark scribe visible.
Orig. 36" now 58" Fir, S.70°W., 21.1 ft., bark scribe visible.
Tree blown down at N.12°W., 58.1 ft., but could not find any scribing.

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 6 W
S 6 | S 5
S 7 | S 8
1965

New BTs -50" Fir N.85°E., 22.6 ft. scribed T32S R6W S5 CS BT.
53" Fir S.70°W., 22.5 ft. scribed T32S R6W S7 CS BT.
48" Fir N.83°W., 64.4 ft. scribed T32S R6W S6 CS BT.
No tree in SE quad., clear cut.

Corner is now cutting corner and about 300.0 ft. South of old cabin.

Fd. B.C.; 2 Orig. BTs,; 1 1965 BT, - in BLM survey by G. Steven Popken, under Group #883, surveyed Sept. 1975 (DCSO records, Vol. 37 Page 15379)

(Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley, L.S. #2354 - For: Kenneth Ford - Oct. 1994 - M
121-7

Found - 1965 County BCIP.
53" Fir, N.81°E., 22.4', protected stump, 0BT.
New BTs- 9" Fir, S.2°W., 37.3', "S 7 BT".
9" Fir, S.57½°W., 39.0', "S 7 BT".
5" Fir, S.61°e., 22.3', tagged only.
Timber has been clearcut on 3 sides of this corner.

FD. OK BY Carl Sweeden - June 7, 2004 - C.S. File 65/49-40