

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 and 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by George W. Hyde and Charles H. Gardner, Deputy Surveyors, under Contract #54, dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8643)

Set post cor. to secs. 32 and 33, from which
A Fir 18" dia., bears N.45°W., 28 lks. dist.
A Fir 7" dia., bears N.33°E., 28 lks. dist.

H.L. Eppstein, Co. Surveyor - Wit: B.A. Lane; J.H. Wolford - June 12, 1929 - C.S. File 14/1 (and "old" corner book, page 172)

Old stake. 2" iron pipe for corner. Marked new witness trees:
An 8" Apple N.80°30'W., 56 lks.
An 8" Apple N.81¼°E., 60 lks.
(The 24" Fir for secs. 4 and 5, bears S.79½°E., 191 lks.)

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Joe Brady, crew - Sept/Oct. 1967 - C.S. File 54/53-41

Found - 2" iron pipe not found, has been taken, info from prop. owner C.R. Birchfield.
8" now 14" Apple, N.81°E., 39.6 ft., scribe visible "BT".
No trace of other Apple tree.
Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 6 W
S 32 | S 33
S 5
1967

New Bearing Objects:
PK Nail in base of power pole #E2448, S.87½°W., 75.6 ft.
PK Nail in base of power pole #E2422, S.87°E., 43.0 ft.
This corner lies on North edge of road approx. 175 ft. West of Third Street.

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - L.E. Monrean; P. Earle; S. Flause, crew - May 22, 1979 - C.S. File 60/24-34

Found - A 1" iron pipe with brass cap attached at location determined by Eppstein. Cap set by Powell mkd. "County Surveyors Office T32S R6W S32 S33 S5 T33S 1967" (Cont. Next Page)

TOWNSHIP 32 RANGE 06 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 and 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An Apple tree, 8" now 15" with fragmentary scribing visible bears N.81°E., 39.0 ft. 9Rec. N.81°E., 39.6 ft.)
Power poles referred to by Powell have been replaced
No new monument set.
New Accessory:
A 27" man hole collar marked "B.O." on South edge, center punch bears S.63°W., 23.84 ft. (Note: bearing and distance to center punch in "B.O" mark)

Cor. Fd. OK, Greg Lang, Feb. 1990, M 110-6

Found OK, 12/95 by Nygren - Outback Estates Vol. 18 Pg. 56
