

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36 T31-6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - George W. Hyde under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 19 Page(s) 7947)

-
- Set post cor. to secs. 1, 2, 35 and 36, from which
- A Fir 8" dia., bears N.28°E., 6 lks. dist.
 - A Fir 6" dia., bears S.53°E., 50 lks. dist.
 - A Fir 14" dia., bears N.30°W., 59 lks. dist.
 - A Fir 18" dia., bears S.60°W., 47 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - For: C & D Lumber Co. - April 2, 1963 - C.S. File 53/12 and M 25-10

-
- Found - Orig. 14" now 30" Fir N.30°W., 38.9 ft. shows scribe marks on partly rotted face.
Orig. 6" now down 12" Fir, S.53°E., 33.0 ft. shows scar.
No other orig. BTs found.
- Set 3/4" Iron rod at corner.
- New BTs -12" Hemlock bears N.80°W., 50.0 ft. scribed S35 T31S R6W CS BT.
12" Hemlock bears S.12°E., 3.5 ft. scribed S1 T32S R6W CS BT.
9" Cedar bears East, 43.1 ft. scribed S36 T31S R6W CS BT.

BLM resurvey by Rollin D. Aanrud, Cadastral Surveyor, under Group #1018, surveyed June/Aug. 1980 (DCSO records Vol. 44 Page(s) 16982-83)

-
- The sec. cor., perpetuated and recorded by Byron in 1963, monumented with an iron rod, 3/4" dia., firmly set, projecting 4" above ground, from which the remains of the original bearing trees:
- A root hole, bears S.53°E., 50 lks. dist., with a down Fir alongside, 12" dia., with healed blaze.
 - A Fir 30" dia., bears N.30°W., 59 lks. dist., with healed blaze.
- and bearing trees mkd. by Byron
- A Cedar 9" dia., bears N.84 3/4°E., 67 lks. dist., with scribe marks S36 T31S R6W CS BT visible on open blaze.
 - A Hemlock 16" dia., bears S.12°E., 5 lks. dist., with healed blaze.
 - A Hemlock 18" dia., bears N.80°W., 77 lks., dist., with scribe marks S35 T31S R6W CS BT visible on partially healed blaze.
- At the corner point
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. cor. for 1 & 2; 35 & 36, T31-6

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, directly over iron rod, with brass cap marked

T 31 S R 6 W
S 35 S 36
 S 2 S 1
 T 32 S
 1980

from which a new bearing tree
 A Hemlock 6" dia., bears S.75°W., 46 lks. dist., mkd. T32S R6W S2 BT.

Lloyd D. Smith, L.S. #1101 - For: State of Oregon, Dept. of Forestry - June 1995 - M 122-15

Found - BLM P/C, 1980
 6" Hemlock, (1980) S.75°W., 46 lks., (now 6"x15' long wind fall face down)
 All other trees now missing in road r/w clearing.

New Accessories -
 10" Fir, S.78°E., 121.2', scribed (T32S R6W S1 BT)
 WP (Orange carsonite marker CBM-250R Labeled witness post) N.43°W., 2.6' to base.
 WP (Orange carsonite marker CBM-250R Labeled witness post) N.73°E., 2.7' to base.

Corner lies 6.0' South from top edge of gravel road cut bank.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - July 24, 1996 - C.S. 64/69-16

Mon. Fd.- 3 1/4" dia. Brass cap on a 2 1/2" o.d. iron pipe protrudes 8" above ground.

Bt's Fd.- No OBT's Fd.
 21" now dia. hemlock, with a fully healed double blaze, bears S.12°E., 3.5'.
 11" dia. D.Fir, with an unhealed single blaze, scribe visible "T32S R6W S1 BT", bears S.81 1/4°E., 121.2' (record per BT Tag dated 5-24-95 is N.78°W., 121.2') 1995? M122-15.
 Note: BT tag has initials LDS & TW

New Bt's- 36" dia. 2 1/2" high D.Fir, with a 8" long boat spike set through a BT tag near top center of stump. top of BS is stamped "BO 1". BS bears S.50 1/4°W., 29.7'.
 3" Pistol butt D.Fir, double blazed and scribed "X BT" center of trunk, bears N.42 1/2°E., 64.1'. Note: Lower blaze is 1 1/2' above ground.

