

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8722)

Set a Yew post 4 ft. long, 4" sq., 18" in the ground for the 1/4 sec. cor. marked 1/4 S on N. side, from which
A Fir 36" dia., bears S.45°E., 10 lks. dist., mkd 1/4 S BT.
A Fir 36" dia., bears N.45°W., 10 lks. dist., mkd 1/4 S BT.

Survey by Howard Johnstone - For: Roseburg Lumber Co. - Feb. 1969 - M 33-49

Found 2 original BTs.
Set 1 1/2" x 28" I.P.
Scribed -5" W.Fir N.67°E., 29.5 ft.
5" W.Fir S.63°W., 45.1 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, Cliff Stone, crew - Dec. 9, 1966 - C.S. File 54/36-88

Found - 36" now 32" Fir N.45°W., 6.6 ft., bark scribed, 1/4 S BT.
36" Fir, now stob, S.45°E., 6.6 ft. bark scribed, 1/4 S BT.
1" Iron pipe at 1/4 corner. (See M 33-49)
New BT - 22" D.Fir S.27°W., 14.1 ft. mkd. 1/4 S12 CS BT.
Johnstone BT -
6" D.Fir N.67°E., 29.5 ft. mkd. 1/4 S1 BT.
This corner lies 20.0 ft. N. of skid road and 125.0 ft. W. of logging road. E-W line crosses just South of bridge.

Fd. OK, March 1970 - DCSO JP C.S. File 54/36-106