

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 164100

PRIMARY CORNER DESCRIPTION C.C. for Secs. 5 & 6, T33-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Norman D. Price, U.S. Surveyor, under Group #33, Surveyed May/June 1919 - C.S. File 64/76-1

At point of intersection (15.73 chs., S.89°51'W. from standard cor. of secs. 31 and 32), Set a diorite stone 15x8x6 ins., 10" in the ground, for closing cor. of secs. 5 and 6, mkd. CC on S.; with 5 grooves on E. and 1 groove on W. face; from which

A Fir 18" dia., bears S.30°E., 80 lks. dist. mkd. T33S R8W S5 CC BT.

A Fir 24" dia., bears S.48°W., 38 lks. dist. mkd. T33S R8W S6 CC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-20

Found - 15x8x6 stone at corner, marks visible "C" and grooves.

24" D.Fir now snag, S.48°W., 25.1 ft., tree previously opened, scribe visible "6 CC".

18" now 30" D.Fir S.30°E., 15.8 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T32S R8W
S 31
CC S 6 | S 5
T33S R8W
1968

New bearing object:

R.R. Spike in top of 48" Fir stump, S.41°W., 40.6 ft
Area logged, no trees.

Corner lies on top of ridge, running E-W.