

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 371100

PRIMARY CORNER DESCRIPTION C.C. for Secs. 3 & 4, T33-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Norman D. Price, U.S. Surveyor, under Group #33, surveyed May/June 1919 - C.S. File 64/76-1 (67)

At point of intersection (9.63 chs. N.89°18'W. from the standard cor. of secs. 33 and 34)

Set a diorite stone, 16x8x6 ins., 11" in the ground, for closing cor. of secs. 3 and 4, mkd. CC on S.; with 3 grooves on E. and W. faces; from which

A Fir 36" dia., bears S.13°E., 60 lks. dist. mkd. T33S R8W S3 CC BT.

A Fir 48" dia., bears S.62°W., 62 lks. dist. mkd. T33S R8W S4 CC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-19

Found - Corner stone 16x8x6 mkd. 3 notches on E. & W. sides. 36" now 41" D.Fir S.13°E., 39.6 ft., shows good face 48" now 51" D.Fir S.62°W., find dist. to be 36.0 ft. & orig. dist. was 40.9 ft., slope dist. shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
Doug. Co.

R8W T32S S 33 CC
T33S S 4 | S 3
Jos. Co.
1968

All trees are in good condition.
Corner lies E. approx. 125.0 ft. from a spur.