

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor under contract # 474 dated May 10, 1883 (DCSO records Vol. 21 Page(s) 8809-10

A Live Oak, 8" dia., which I marked ¼S on W face for the ¼ sec. cor. & from which

A Live Oak, 6" dia., bears S.85°E., 15 lks., mkd: ¼ S BT.
A Live Oak, 5" dia., bears West, 4 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John Powell - 3/1968 - C.S. file 54/65-3

Reported as not found
Not found, however found probable old BT down. Old axe work no evidence of any scribe work.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #2004, survey March/Oct. 2002- (DCSO records Vol. 54 Page(s) 21094)

Point for the ¼ sec. cor. of secs. 9 and 10 at proportionate distance, there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

T 32 S R 8 W
1/4
S 9 | S 10
2002

from which

A fir, 11" dia., bears S.19°E., 30.7 ft., mkd. ¼ S10 BT.
A live oak, 6" dia., bears S.15¼°W., 13.2 ft., mkd. X at breast height and BT at base.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

Fd. Ok by D. Edwards, 8/2005 - M148-31