

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 258700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only, T31-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8171)

Set a Fir post 4" sq., 4 ft. long, 24" in the ground for cor. to secs. 32 and 33, mkd. T31S S33 on NE.; R9W S32 on NW.; also 4 notches on E. and 2 notches on W. edge, from which
A Fir 12" dia., bears N.35°E., 22 lks. dist. mkd. T31S R9W S33 BT.
A Fir 8" dia., bears N.80°W., 10 lks. dist. mkd. T31S R9W S32 BT.

GL0 Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12193)

Intersect at the cor. of secs. 32 and 33, which is a Cedar post, firmly set, mkd. and witnessed as described by the surveyor general, except that the NW. BT is dead. I perpetuate this corner as follows: alongside the old cor. Set an iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 32 and 33, with brass cap mkd.

T31S	R9W
S 32	S 33
1917	

from which
A Fir 14" dia., bears N.33°E., 23 lks. dist. mkd. T31S R9W S33 BT. (Old BT)
A Fir 18" dia., bears N.29°W., 50 lks. dist. mkd. T31S R9W S32 BT. (New BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - March/April 1967 - C.S. File 54/32-55

Found - GL0 brass cap at cor. properly mkd. in 1917.
Orig. 14" D.Fir N.33°E., 15.0 ft., opened for scribe "T"., burned face.
18" now 20" D.Fir N.29°W., 33.0 ft., shows scar.
New BT - 13" D.Fir N.42°W., 30.3 ft. mkd. T31S R9W S32 CS BT.
Reblazed and rescribed:
14" D.Fir N.33°E., 15.8 ft. mkd. T31SR9W S33 CS BT