

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 318700

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 33 only, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8171)

Set a Fir post 3 ft. long, 4" sq., 24" in the ground mkd. S33 1/4 S on N. face, for the 1/4 sec. cor., from which

A Chinquapin 14" dia., bears N.75°E., 93 lks. dist. mkd. S33 1/4 S BT.

A Chinquapin 14" dia., bears S.85°W., 300 lks. dist. mkd. S33 1/4 S BT.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12192)

Intersect at the 1/4 cor. of sec. 33, which is a decayed post, firmly set, mkd. and witnessed as described by the surveyor general, with the exception that the S. BT is 30 lks. dist. instead of 300 lks. dist., as given in the field notes. I perpetuate this cor. as follows: alongside the old cor.

Set an iron post 3 ft. long, 2" dia., 26" in the ground for 1/4 cor., with brass cap mkd. 1/4 S 33
1917

from which

A Chinquapin 20" dia., bears N.76°30'E., 94 lks. dist. mkd. 1/4 S33 BT. (Old BT)

A Fir 36" dia., bears N.25°W., 81 lks. dist. mkd. 1/4 S33 BT. (New BT)