

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12189)

Set an iron post 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 2 and 3, with brass cap mkd.

S 3 | S 2
T32S | R9W
1917

from which

A Fir 60" dia., bears S.82°E., 70 lks. dist. mkd. T32S R9W S2 BT.

A Fir 36" dia., bears S.39°W., 29 lks. dist. mkd. T32S R9W S3 BT.

Cor. Fd. OK, 1967 by DCSO, J.Powell - C.S. File 54/32

Tony Hostetter - For: Plum Creek. Co. - Dec 2010 - M161-80

Found - 1917 brass cap & BTs (now stumps) as described by Mensch Vol. 29 Pg. 12189

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - Feb. 9, 2011 - C.S. File 67/33-7

Found - 1917 brass cap 2½" dia., (properly) marked on a 1½" I.D. galv. iron pipe firmly set and protruding 1 ft. above ground.

A fir 60" dia. now a partially rotted backless 4½ ft. tall 60" dia. fir stump with no blaze or scribing evident, bears S.82°E., 46.2 ft. (as per rec) Stump has metal cap. 1917

A fir 36" dia., now a 38" dia., 3 ft. tall, backless but solid fir stump with a fully healed single blaze, bears S.39°W., 19.1 ft. (as per rec.) stump has metal cap. 1917

New - A 5" DBH D.Fir scribed "X" "CS BT" on a high-low blaze; bears S.21½°W., 11.7 ft.

An 18" DBH D.Fir scribed "T32S R9W S3 CS" "BT" on a double blaze; bears S.65½°W., 45.1 ft.

Note - Monument is on moderate southerly slope near top of broad NE running ridge. There is a large new clear-cut North of the E-W section line. Monument is approx. 250 ft east from a graveled BLM rd. Compass decl. 16°E.