

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 2 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12188)

Set an Iron post 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor. of sec. 2 only, with brass cap mkd.

1/4 S 2
1917

from which

A Fir 30" dia., bears S.24°E., 63 lks. dist. mkd. 1/4 S2 BT.

A Fir 30" dia., bears S.55°W., 8 lks. dist. mkd. 1/4 S2 BT.

Fd. OK, by DCSO, J. Powell - 1967 - C.S. File 54/32

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 3/28/2011 - C.S. File 67/36-12

Found - A 2 3/8" dia. brass cap (properly mkd) on a 3/4" ID iron pipe, firmly set & protruding approx. 1 ft. above ground. 1916-1917

BC lies N.89 1/2°W., 34.0 (1916 rec. N.89 1/2°W., 35.0 ft) from AP on north boundary of Sec. 2, T32-9; IE the center of the fir original established as the quarter corner in 1883.

From the original 1916-1917 BC

30" fir now 42" DBH D.Fir with low fully healed single blaze; bears S.24°E., 41.6 ft (as per rec)

30" fir now 37" fir DBH D.Fir with high fully healed single blaze; bears S.55°W., 5.3 ft. (as per rec)

New - An 11" DBH chinquapin scribed "1/4 S2 CS" "BT" on a double blaze; bears S.10 1/2°E., 20.4 ft.

Note - Monument is on a steep hillside, an old clear cut with mix regrowth of Oak and Fir to the North & an old growth stand of Fir and mixed hardwood to the south.

Compass decl. 16°E.