

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION SE. Cor. Sec. 36 (SE Tsp Cor.)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8774 & 8775)

Set a Fir post 4½ ft. long, 4" sq., 24" in the ground for the standard cor. to Tps. 32 South, rgs. 8 and 9 West, mkd. T32S on N.; R9W S31 on E.; and R9W S36 on W. faces; also 6 notches on the NE. and W. faces of same, and from which
A Chinquapin 10" dia., bears N.58°E., 27 lks. dist. mkd. SC T32S R8W S31 BT.
A Fir 6" dia., bears S.47°E., 14 lks. dist mkd. SC T33S R8W S6 BT.
A Fir 10" dia., bears N.82°W., 16 lks. dist. mkd. SC T32S R9W S36 BT.

Fd. and tied corner in BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8859)

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12196)

The standard cor. of Tps. 32 S., Rs. 8 and 9 West, which is a Fir post, firmly set, with the exception that the NE. bearing tree is now dead. I perpetuate this cor., as follows: alongside the old cor.
Set an Iron post 3 ft. long, 3" dia., 24" in the ground, for standard cor., with brass cap mkd.
S C
T 32 S
R9W|R8W
S 36|S 31
1917

from which
A Fir 8" dia., bears N.32°E., 29 lks. dist., mkd. SC T32S R8W S31 BT. (New BT)
A Fir 14" dia., bears N.82°W., 16 lks. dist., mkd. SC T32S R9W S36 BT. (Old BT)

DCSO-GIS Corner visitation - 2/5/2004 - Typed: 2/10/2011 - C.S. File 67/33-1

Monument - 2.5" IP/BC Comment - ok