

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 206700

PRIMARY CORNER DESCRIPTION A P No Bdy Sec 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Butler Ives and George W. Hyde, under Contract #39, dated January 4, 1854 - (DCS0 records Vol. 20 Page(s) 8550)

Set post cor. of secs. 31, 32, 5 and 6, from which
A Dogwood 5" dia., bears N.35°W., 52 lks.
A Fir 14" dia., bears N.32°E., 37 lks.
A Laurel 10" dia., bears S.10°E., 29 lks.
A Laurel 10" dia., bears S.40°W., 45 lks.

GL0 survey by Edward F. Sharp, Deputy Surveyor, under Contract #617, dated June 3, 1893 (DCS0 records Vol. 21 Page(s) 8998)

Intersect cor. to secs. 31 and 32, T32S R5W determined by bearing trees as post was missing. At point for cor. set a quartz stone 10 x 8 x 8 ins., 7" in the ground for cor. to secs. 31 and 32, T32S R5W marked with 5 notches on the E. and 1 notch on the W. edges, from which
A Fir 14" dia., bears N.32°E., 37 lks. dist. with well defined blazes.
A Laurel 10" dia., bears S.40°W., 45 lks. dist. with well defined blazes.
The SE and NW trees being burnt down with marks partly grown over, I reestablish
A Fir 30" dia., bears N.42°W., 64 lks dist., marked T32S R5W S31 BT.
A Fir 24" dia., bears S.41°E., 100 lks. dist. marked T33S R5W S5 BT.

George J. Wenderoth - For: Geo. Newman - 1953 - C.S. file 49/112

Find old original corner 84.5 ft. East of C.C. to secs. 31 and 32. Find:
30" Fir N.42°W., 42.2 ft., stump scribed.
24" Fir S.41°E., 66.0 ft., stump scribed.

BLM dependent resurvey by Terrence O. Nickerson, Cadastral Surveyor under Group #1474 survey Feb. 1989/June 1992 - (DCS0 records Vol. 53 Pg(s) 20353)

Beginning at the former standard cor. of secs. 5, 6, 31, & 32 on the N. bdy of T33S, R5W, now an angle point, determined at record distance from the remains of an OBT:
A Fir stump, 40" dia., bears N.35½°E., 37 lks., no mks visible on chopped out face. (Rec. N.32°E.)
and remains of BTs mkd. by Sharp (continued next page)

TOWNSHIP 33 RANGE 05 POINT IDENTIFIER # 206700

PRIMARY CORNER DESCRIPTION A P No Bdy Sec 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A sawed Fir stump, 42" dia., bears S.41°E., 100 lks., no marks visible on chopped out face.
A sawed Fir stump, 44" dia., bears N.42°W., 64 lks., with fragmentary scribe marks visible on chopped out face.
and BTs from which there is no known record
A Fir, 20" dia., bears N.71½°E., 39 lks., with healed double blaze.
A Fir, 13" dia., bears N.30¼°W., 11½ lks., with healed double blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap marked:
T32S R5W
AP
S 32
S 5
T33S
1989
from which a new BT
A Hemlock, 10" dia. bears S.30½°E., 19 lks. mkd: AP S5 BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Found OK by M. Hull, Feb. 2004 - M144-18

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 3006; Surveyed April 2021/Nov. 2022 - (DCS0 records Vol. 59 Page(s) 24116-7)

The Angle Point bet. secs. 5 and 32, reported by Nickerson in 1989-92, monumented with a stainless steel post, 2½" dia., firmly set, projecting 6" above the ground, with brass cap (properly)mkd.
from which the remains of bts reported by Nickerson
A rotted fir stump, size indeterminate, bears S.41°E., 66.0 ft., no marks visible.
A hemlock, 12" dia., bears S.30½°E., 12.5 ft., with a healed blaze.
A fir stump, 16" dia., bears N.30¼°W., 7.6 ft., with a healed blaze.
and a new bearing tree
A fir, 5" dia., bears N.40½°W., 13.2 ft., mkd. X at breast height and BT at the base.
Note - Each new BT has a 2½"x¼" magnetic nail (Mag Nail) driven at the base on right side center and each monument established or reestablished has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.