

Subdivisions of T. 22, S., R. 9 W.

CHAINS		
	Ascend.	
40.16	To a point 165 lks. North of the $\frac{1}{4}$ sec. corner, which is a Fir, 30 ins. diam., marked $\frac{1}{4}$ S. on the N. side. Continued N.89*39' from the $\frac{1}{4}$ sec. corner.	
44.00	Trail and top of ridge, Course N. and S.	+ 150
80.60	To a point 87 lks. North of the corner to secs. 25, 30 31 and 36, which is a post 2 feet above ground, 4 ins. square on point of hill sloping SW., marked T. 22 S., S. 30 on the NE., R. 9 W., S. 31 on the SE., R. 10 W., S. 36 on the SW., and S. 25 on the NW., faces with 1 notch on the S. and 5 notches on the N. edges, from which, A Fir, 20 ins. diam., bears N.1*E., 67 lks. dist. Marked T. 22 S., R. 9 W., S. 30 B. T. A Fir, 18 ins. diam., bears S. 25*E., 35 lks. dist. Marks grown over. A Fir, 20 ins. diam., bears S.34*W., 41 lks. dist. Marks grown over. A Fir, 14 ins. diam., bears N.40*W., 24 lks. dist. Marked T. 22 S., R. 10 W., S. 25 B. T. Practically agreeing with notes furnished me by the U. S. Surveyor General. Land, mountainous. 80.60 chs. Soil, second rate. Timber, Fir, Hemlock, Cedar and Maple. Undergrowth, dense, vine-Maple, Hazel, Salalberry, Rhododendron and Arrow wood. 80.60 chs. March 30, 1895.	