

Meanders of T. 22 S., R. 10 W.

CHAINS	<u>Course</u>	<u>Chains</u>	
			Narrow bottom land, 1st rate. Claim corners undefined.
			In sec. 24.
	N.65*E.	18.00	
	N.69*E.	6.14	To M. P.
			Narrow bottom along river, 1st rate. Timber, poor. Underbrush, same as previous.
			In sec. 13.
	N.49*E.	20.00	Narrow bottom.
	N.74 $\frac{1}{2}$ *E.	45.18	At 44.50, a creek, 50 lks. wide. To M. P.
			Narrow bottom along the river. Saw Mill (Scotts) on the creek was taken off by the freshet of 1861 & 2. Also the entire lower Scottsburg. But little trace now remains.
			July 2, 1874.
<u>General Description</u>			
This township is of little value except the narrow bottoms along the river and a few fractions of mountains near river for timber.			
The timber has generally been taken off or burned by the fires that have raged along the mountains from time to time.			
Six or seven claims are located along the river. Principally "Donations."			
The river is run almost daily by a steamer and other boats. It is a good navigable stream for vessels of light draft.			