

Subdivisions of T. 22 S., R. 10 W.

CHAINS	
78.00	Spur, course S.40*E.
80.30	The cor. to secs. 4 & 9. Land, mountainous, 80.30 chs. Soil, rocky, 4th rate. Timber destroyed by fire. Dense undergrowth of thimbleberry, cherry, vine maple, hazel, sallal, manzanita & tar balm. Aug. 21, 1894.
	North, 0*8'W. on a random line bet. secs. 4 & 5. Var. 20*30'E.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
93.15	Intersect N. bdy. line at the cor. to secs. 4 & 5. Thence I run S.0*8'E. on a true line bet. secs. 4 & 5. Var. 20*30'E.
	Ascend.
6.50	Ridge, course SE.
7.00	Same ridge, course S.
17.00	Leave ridge, course SE.
52.80	A fir, 48 ins. diam., on line marked with 2 notches on N. & S. sides.
53.15	An alder, 5 ins. diam. which I marked $\frac{1}{4}$ S. on N. for $\frac{1}{4}$ sec. cor. from which An alder, 6 ins. diam., bears S.58*E. 25 lks. dist. marked $\frac{1}{4}$ S B T. An alder, 8 ins. diam., bears S.20*W. 18 lks. dist. marked $\frac{1}{4}$ S B T.
55.00	Spur, course SW.
84.50	Spur, course E. Descend to
93.15	The cor. to secs. 4 & 9. Sand, mountainous, 93.15 chs. Soil, rocky, 4th rate. Timber destroyed by fire.

+200