

SUB-DIVISIONS OF T. 22 S., R. 12 W. W.M.

CHAINS

20 ins. in ground for the  $\frac{1}{4}$  Section corner between Sections 23 and 24, from which

A Fir, 8 ins. diam., bears N.32\*E., 20 lks. dist.

A Fir, 36 ins., diam., bears S.30\*W., 29 lks. dist.

45.50 Creek 5 lks. wide course SW.

52.50 Creek 2 lks. wide course W.

80.00 Marked a Maple 8 ins. diam., for the corner to

Sections 23, 24, 25 and 26 from which

A Maple, 8 ins. diam., bears N.50\*E., 12 lks. dist.

A Fir, 10 ins. diam., bears S.65\*E., 40 lks. dist.

An Alder, 36 ins. diam., bears S.30\*W., 39 lks, dist.

An Alder, 36 ins. diam., bears N.89\*W., 70 lks. dist.

Land, broken mountainous, 3rd rate.

Timber chiefly Fir 2nd rate.

Undergrowth with Vinemaple and Salmonberry brush.

June 9th, 1879.

Beginning at the established corner to Sections 14, 15, 22 and 23, (corner and trees all standing and agreeing with notes furnished from the Surveyor General's office,) I run

South on true line between Sections 22 and 23.

Va. 18\*East.

22.50 Top of ridge course SW and NE.

39.75 A creek 3 lks. wide course E.

40.00 Marked an Elder 5 ins. diam., for the quarter section corner between Sections 22 and 23, from which

A Maple, 10 ins. diam., bears S.15\*E., 30 lks. dist.

An Alder, 16 ins. diam., bears N.25\*W., 68 lks. dist.

43.00 A creek 2 lks. wide course NE

54.50 A creek 1 lk. wide course NE

62.00 Top of Spur course NE and SW.

79.00 A creek 2 lks. wide course NE.

80.00 Set a Fir post 40 ins. long, 20 ins. in ground, for the