

Subdivisions of T. 23 S., R. 7 W., W. M.

CHAINS	
	Land East part broken, 2nd rate. West part hilly, 2nd rate. Timber on East part young fir. Prairie glades on west.
	From the post set for the cor. to secs. 3 & 10 I run North between secs. 2 & 3. Va. 19*E.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.46	Intersect North boundary of township 1.90 lks. East of cor. to secs. 2 & 3, thence: South ^{1° 21' (PER PLAT & MICROFILM) 11/16/21 R.} 7*21' East on true line between said secs. 2 & 3. No evidence of old line to be found.
25.00	Creek 5 lks. wide, course SW.
49.46	Set a fir post for the $\frac{1}{4}$ sec. cor. to sec. 2, from which, A fir, 12 ins. diam., bears N.11*E., 13 lks. dist. A fir, 10 ins. diam., bears N.72*W., 124 lks. dist.
55.46	Enter field. Leave timber, course E & W.
75.46	Leave field.
80.46	To sec. cor. North part mountainous, timbered chiefly fir & cedar South part 1st rate, prairie and glades. Feb. 19th 1881.
	The quality of the lands of this fractional township is varied. Only a small portion 1st class. The remainder is 2nd & 3rd class lands covered with a fine growth of fir, cedar, hemlock, oak, maple, alder, chinquapin, yew, and laurel timber, generally of an excellent quality. There are some four settlements made One in sec. 23, One in sec. 14 and two in sec. 2. Several other localities are susceptible of cultivation.