

Retracement of E Bdy. of T. 24 S., R. 2 W.

CHAINS	
40.00	Make diligent search for $\frac{1}{4}$ sec. cor., but fail to find any trace thereof
72.60	Intersect E and W line, 1047 lks. W of cor. of secs. 7, 18, 13 and 12, which is a post, 4 ft. long 4 ins. sq. set 24 ins. in the ground, marked and witnessed, as described by the surveyor general Therefore, this line, bears N.8*12'E., and is 73.42 chs. in the length This cor. is correct in position.
40.00	<i>Thence I run</i> North, on blank line, bet. secs. 7 and 12 No evidence of a $\frac{1}{4}$ sec. cor. is found
79.81	Intersect E and W line, 1 lk. E of cor. of secs. 6, 7, 12 and 1, which is a post, 4 ft. long, 4 ins. sq. 24 ins. above ground, marked and witnessed, as described by the surveyor general Therefore, this line bears N
39.57	<i>Thence</i> North, on a blank line, bet secs. 1 and 6 From this point, the $\frac{1}{4}$ sec. cor. bears W, 7 lks. dist. This cor. is a post, 3 ins. sq. 12 ins. above ground, marked and witnessed as described by the surveyor general
79.55	Intersect E and W line, 13 lks. E of cor. of Ts. 24 and 23 S, Rs. 1 and 2 W, which is a post 2 ft. above ground 4 ins. sq. marked and witnessed, as described by the surveyor general Therefore, this line bears N.6'W, and is 79.55 chs. in length
July 22, 1896	

General Description

Township 24 South, Range 1 West, lies in a mountainous district. There is no land in the whole township that can be cultivated, the character of the land being too precipitous, and the altitude, too great.