

Retracements of South Boundary T. 24 S., R. 8 W.

CHAINS

80.08 Cor. of Secs. 4, 5, 32 and 33, which is a sandstone, firmly set, marked and witnessed as described by the Surveyor General, bears S. 118 lks. dist. I destroy all marks referring to Secs. 3 and 4, on Fir S.60°E., from cor.

The true course of this line is S.89°9'W., and the length is 80.09 chs.

Note :- Old survey did not go over 800 ft. cliffs where we went on true line, must have broken their survey line and gone around cliffs.

Land, mountainous.

Soil, 2nd and 3rd rate.

Timber, heavy Fir, Hemlock and Rhododendron.

Mountainous land, covered with heavy timber and dense undergrowth, and exceptionally difficult to survey.

80.09 chs.

June 18th, 1911.

At the cor. of Secs. 32 and 33, on S. bdy. T 24 S., R. 8 W.

Thence

West, on retracement of S. bdy. Sec. 32.

0.40 Creek, 2 lks. wide, course N.

Ascend steep ridge, in heavy timber and dense undergrowth.

8.20 Top of ridge, bears N. and S., descend.

21.30 Creek, 2 lks. wide, course NE., ascend.

29.42 No trace of old $\frac{1}{4}$ sec. cor. can be found after diligent search.

40.00 No trace of $\frac{1}{4}$ sec. cor. can be found after diligent search.

41.45 Top of ridge, bears N. and S., descend.

Descend long ridge, in heavy timber and dense undergrowth.

52.00 Dry canyon, course S., ascend.