

Subdivisions of T. 24 S., R. 9 W., N. M.

CHAINS	
66.00	Lake creek, 100 lks. wide, course NW.
80.36	To Sec. corner. Land, east part, hilly; 2nd rate. west part, bottom; 1st rate. Description of timbers, same with the addition of Ash & maple in the bottoms. May 5, 1879
40.00	North, on true line between Secs. 10 & 11. Va. 18°30'E. Marked a maple, 4 ins. dia., for the $\frac{1}{4}$ Sec. corner between Secs. 10 & 11, from which a, Fir, 18 ins. dia., bears N.55°E., 9 lks. dist. Fir, 30 ins. dia., bears S.60°W., 9 lks. dist.
63.50	Lake creek, 100 lks. wide, course NW.
80.00	Set fir post on East bank of creek, 40 ins. long 4 ins. dia., 20 ins. in ground for the corner to Secs. 2, 3, 10 & 11, from which a, Fir, 24 ins. dia., bears N.65°E., 40 lks. dist. Fir, 36 ins. dia., bears S.50°E., 26 lks. dist. Fir, 36 ins. dia., bears S.15°W., 76 lks. dist. Chitemwood, 8 ins. dia., bears N.3°W., 145 lks. dist. Lands, nearly level, 1st rate. Timber, same as former line.
40.00	East on random line between Secs. 2 & 11. Va. 18 $\frac{1}{2}$ °E. Set temporary $\frac{1}{4}$ Sec. corner.
80.15	Intersect line, 63 lks. S. of corner. S.89°33'W., on true line.
40.07	Set Alder post 4 ins. dia., 40 ins. long, 18 ins. in ground for the $\frac{1}{4}$ Sec. corner between Secs. 2 & 11, from which a, Fir, 16 ins. dia., bears S.65°W., 17 lks. dist. Fir, 14 ins. dia., bears N.70°W., 19 lks. dist.
80.15	To section corner. Land, sloping south & west, 2nd rate. Timber & underbrush unchanged, bottom along creek narrow.