

Subdivisions of T. 25 S., R. 8 W.

CHAINS

48.50 Stream 3 lks. wide course SE.
 56.50 Summit of main ridge SE. & NW. (Coos Bay trail)
 60.50 Perpendicular bluff 150 ft.--from the top ran N.
 78.50 Stream 5 lks. wide course SE.
 80.00 Cor. to secs. 16, 17, 20 & 21
 Set post from which
 A fir, 14 ins. diam., bears N.60*W. 13 lks. dist.
 A fir, 14 ins. diam., bears N.10*E. 27 lks. dist.
 A chinapin, 12 ins. diam., bears S.55*E. 49 lks.
 dist.
 A hemlock, 6 ins. diam., bears S.40*W. 17 lks. dist.
 Land 4th rate
 Timber fir, cedar, hemlock
 This mile is terribly rough, rocky & broken
 Oct. 3, 1881

East, on random line between secs. 16 & 21

Var. 183/4*E.

4.50 Stream 2 lks. wide course SE.
 5.50 Stream 6 lks. wide course NE.
 19.00 Summit of ridge N. & S.
 35.50 Summit of ridge NE. & SW.
 40.00 Set temp. $\frac{1}{4}$ post
 80.88 Cor. secs. 15, 16, 21 & 22
 Intersect line 40 lks. S. of cor.
 Thence I ran S.89*43*W. on true line bet. secs. 16 & 21
 40.44 Set dogwood $\frac{1}{4}$ sec.post 3 ft. long 3 ins. sq. from which
 A fir, 30 ins. diam., bears S.20*W. 17 lks. dist.
 A maple, 8 ins. diam., bears N.35*E. 20 lks. dist.
 80.88 Cor. to secs. 16, 17, 20 & 21
 Land 3rd & 4th rate
 Timber hemlock, fir, cedar, laurel & dogwood
 Undergrowth fir, vine maple & hazle
 Oct. 5, 1881 (Stormy)