

Corrections of the Subdivisions in T. 27 S., R. 8 W.

CHAINS

verify the witnesses and where necessary correct the markings there on to conform to the notes thereof on file in the U. S. Surveyor General's office.

I remeasure the line bet. secs. 2 and 3, thus
N.0*8'W., bet. secs. 2 and 3.

40.00 Qr. sec. cor. as described in original notes

80.01 The cor. to secs. 2, 3, 34 and 35, on N. bdy. of Tp.

From the Std. cor. of secs. 33 and 34, on the S. bdy. of the Tp. I trace without measuring the W. and N. bdys. of the third tier of secs. and examine each cor. verify the witnesses thereto and where necessary correct the markings thereon to conform to the notes thereof on file in the U. S. Surveyor General's office.

From the Std. cor. of secs. 32 and 33, on the S. bdy. of the Tp. I trace without remeasuring the W. and N. boundaries of the fourth tier of secs. and examine each cor. verify the witnesses thereto and wherever necessary correct the markings thereon to conform to the notes thereof on file in the U. S. Surveyor General's office.

I remeasure the line bet. secs. 4 and 5, thus
N.0*3'W. bet. secs. 4 and 5.

39.94 The $\frac{1}{4}$ sec. cor.

79.97 The cor. to secs. 4, 5, 32 and 33, on the N. boundary of the Tp.

From the Std. cor. of secs. 31 and 32 on the South bdy. of the Tp., I trace without remeasuring the West and North bdys. of the fifth tier of secs. and the East half of the West tier of secs., and examine each cor. verify the witnesses thereto and where necessary correct the markings thereon to conform to the notes thereof on file in the U. S. Surveyor General's office.

June 19, 1898

William P. Heydon
U. S. Deputy Surveyor