

## Subdivisions of T. 28 S R 3 W.

CHAINS

28 S R 3 W on S., S 5 on E., and S 6 on W. face,  
with 5 grooves on E. and 1 groove on W. face, from  
which:

A fir, 12 ins. diam., bears S.70°E., 20 lks.dist.

marked T 28 S R 3 W S 5 B. T.

A laurel, 18 ins. diam., bears S.40°W., 20 lks.dist.

marked T 28 S R 3 W S 6 B T.

Land, mountainous.

Soil, rocky- 4th rate.

Timber, cedar, fir and hemlock.

Underbrush, rhododendrons, vine maple and young firs  
and willows.

Land mountainous, covered with dense underbrush and  
heavily timbered and exceptionally difficult to survey.

June 18, 1910.

GENERAL DESCRIPTION

This township is mostly rough and mountainous,  
and contains very little agricultural land. There are,  
however, small tracts of good agricultural land along  
some of the creek bottoms. On nearly every part there  
is a good stand of timber. This is mostly cedar, fir,  
and hemlock. There are numerous settlers in this  
township.

Scott Morrison is located in the southern part  
of section 24 and the northern part of section 25.  
His improvements consist of house, fences, clearing  
and cultivated land and roads with an approximate  
value of \$1200.00

Dudley Fairbanks is located in the NE. 1/4 of  
section 18. His improvements consist of house, fences,  
clearing and cultivated land with an approximate value  
of \$500.00.

Mary Hagan is located in the NE. 1/4 of section  
18. Her improvements consist of house, fence, clear-  
ing and cultivated land with an approximate value of