

Subdivisions of T. 29 S., R. 3 W.

CHAINS

60.00 Top of ridge, C. SW.
 75.74 To sec. cor.
 Land, mountainous, 3rd rate.
 Timber, chiefly fir, cedar and pine.

North, on random line bet. secs. 5 and 6.
 Var. 19*E.

40.00 Set temp. $\frac{1}{4}$ sec. cor.
 71.50 Intersect N. bdy. of Tp. 4.20 chs. W. of cor. to secs.
 5, 6, 31 and 32.
 S.3*22'West, on true line bet. secs. 5 and 6.

31.50 Set an alder post for $\frac{1}{4}$ sec. cor., from which
 A hemlock 16 ins. diam., bears S.25*E., 39 lks. dist.
 A fir, 50 ins. diam., bears N.35*W., 17 lks. dist.

34.00 Creek 5 lks. wide, C. SE.
 48.40 Creek 2 lks. wide, C. E.
 71.50 To sec. cor.
 Land, mountainous, broken, 3rd rate.
 Timber, young fir, cedar, and hemlock.

April 30, 1881

GENERAL DESCRIPTION

The lands of this Township are generally mountainous, 2nd and 3rd rate, except small narrow bottoms along the creeks, generally 1st class

The timbers are generally 1st class, fir, cedar, pine, oak, laurel, maple and ash.

There is one settlement in sec. 8, one in sec. 11, two in sec. 14, two in sec. 15, two in sec. 33 and one in sec. 2. There is a good sawmill in sec. 33 near the center.