

Subdivisions, T. 30 S., R. 1 W.

CHAINS

	East, on true line bet. secs. 1 and 12,	
		Va. 18*30'E.
2.42	A fir 36 ins. diam.	- 10
5.00	Branch 3 lks. wide, C. SE.	- 10
7.68	A spring.	- 5
40.00	A fir, 6 ins. diam., $\frac{1}{2}$ sec. post, from which	- 100
	A fir, 60 ins. diam., bears S.20*E., 11 lks.	
	A fir, 15 ins. diam., bears N.30*E., 20 lks.	
47.40	Branch 2 lks. wide, C. SE.	- 20
52.35	Branch 2 lks. wide, C. S.	- 50
65.00	Branch 5 lks. wide, C. S.	- 20
67.65	Branch 5 lks. wide, C. S.	+ 10
80.00	To corner secs. 1, 12, 6 and 7.	+ 100
	Land about the same as last mile.	

North, on random bet. secs. 1 and 2.

Va. 18*30'E.

40.00	Set temp. $\frac{1}{4}$ sec. post.	
79.88	Intersect N. bdy., 82 lks. E. of corner.	
	South, 0*35'E. on true line bet. secs. 1 and 2.	
20.00	Summit of ridge, C. E. and W.	+ 20
39.88	Set $\frac{1}{4}$ sec. post, from which	- 50
	A hemlock, 6 ins. diam., bears S.26*W., 12 lks.	
	A hemlock 20 ins. diam., bears S.32*E., 24 lks.	
78.56	A fir 48 ins. diam.,	- 50
79.88	To sec. corner.	
	Land about the same as last two miles.	

GENERAL DESCRIPTION

This fractional township is very hilly. The slopes towards the river are generally open and adapted to grazing. The timber is fir, cedar, pine, oak, laurel and maple. Soil, second and third rate.