

Subdivisions of T. 30 S., R. 5 W.

CHAINS	Va. 18° 10' E.	
	North, on random between Secs. 5 & 6.	
40.00	Set temp. $\frac{1}{4}$ sec. post.	
80.80	Intersect North Boundary, 74 lks. East, of Sec. corner.	
	S. 00° 32' W, on true line between Secs. 5 & 6.	level
24.50	Right bank of river, course N. 63° E. Bluff bank.	-30
28.20	Right bank of river bluff.	+25
	Entered prairie bears N. 63° E & S. 27° W. entered	level
	I Weaver's wheat field.	
40.80	Set $\frac{1}{4}$ sec. post at average distance.	
	Made a trench and drove a charred stake, 12 ins. long,	
	at the center point as per instructions.	
80.80	To sec. corner.	
	First rate, soil.	
	Level prairie, lands.	
	July 7, 1854.	

The Northeast, portion of this township, not worth subdividing. This township is composed of hills and small valleys, hills generally timbered and third rate soil, a part of which is prairie. Timber, oak, fir, pine and maple. It is watered by the South fork of the Umpqua River.

Nathaniel Ford
Deputy Surveyor

• Re-survey of
Exterior lines of T. 31 S., R. 5 W, as
Surveyed by William H. Byars, U. S. Deputy Surveyor,
Under his contract No. 456, dated July 28, 1882.

East Bdy.

Not being able to find any trace of the North bdy. of Township 31 South Range 5 West. I re-establish the same, began at the corner to sec. 1, 12, 6 & 7. on the East bdy of the Township, which is a fir post, 4 ins. sq. firmly set in the ground and marked, T 31 S R 4 W S 6 on the NE face, S 7 on the SE face, S 12 on the SW face and R 5 W S 1 on the NW face, also one