

Subdivisions of T. 30 S., R. 7 W., W. M.

CHAINS	<u>General Description</u>
	<p>The lands surveyed in this township are equal to the common average of 2nd. rate lands, the greater portion fit only for grazing purposes.</p> <p>It is well timbered with the usual varieties of fir, pine,, cedar, laurel, oak, yew, maple, ash, etc.</p> <p>Several creeks furnish an unusual amount of water power. Gold is obtained from the bars of Cow creek, and a copper mine considered very rich exists in sec. 36.</p> <p>There are five settlements above miners claims in the Tp . viz; sec. 1, 2, 11, 27, and 36, and a greater portion of the rail road land is already applied for.</p>
	<p>North Boundary of T. 31 S., R. 7 W., W. M. as surveyed by William H. Byars, Deputy Surveyer under contract N. 448; dated June 13, 1882.</p>
	<p>From the cor. to Tps. 30 and 31 S. R 7 and 8 W. I run E. on random line between Tps. 30 and 31 S. R 7 W. N. boundary of sec. 6.</p>
	<p>va. 18° 45' E.</p>
1.50	Begin precipitous, rocky descent.
20.00	Moderate descent.
32.00	Dry ravine, course N.60°E.
35.12-	A creek 2 lks. wide, course N.
37.24	A creek 10 lks. wide, course S.60°E.
38.90	Same creek, 10 lks. wide, course NE.
40.00	Same creek, 25 lks. wide, course SE.
	Set temp $\frac{1}{2}$ sec. cor. Steep rocky bluffs.
46.00	Top of same steep rocky bluff, descend.
51.60	Creek 3 lks. wide, course SW. ascend rocky bluff along SW side of table mountain.
56.00	Along S. slope of mountain, rocky bluff.
76.80	Descend rocky bluff 30 ft., and at
77.00	which is a point due N. of offset cor. established between secs. 5 and 6. Mountain bluff too steep for chaining.