

SUBDIVISIONS OF T. 31 S., R. 9 W.

CHAINS		
45.40	A creek 3 lks. wide, course NE. Steep ascent.	-500
53.00	Top of spur on line, course NE.	+400
71.00	The cor. of Secs. 2, 3, 10 and 11. Land, mountainous. Soil, rocky, 3rd and 4th rate. Timber, Fir, Cedar, Hemlock, Yew, Chinquapin and Laurel. Undergrowth, Fir, Cedar, Hemlock, Yew, Chinquapin, Laurel, Vinemaple, Balm and Vines. Mountainous, heavily timbered or covered with dense undergrowth. 71.00 chains.  May 7th, 1901.	
At the cor. of Secs. 33 and 34 on the S. boundary of the township.		
Thence I run		
N.0°02'W bet. Secs. 33 and 34.		
Ascend.		
4.00	Top of spur, course SW. Descend.	+ 50
12.00	A creek 1 lk., wide, course W. Ascend.	-200
23.50	Top of spur on line, course W. Descend.	+200
31.50	A creek 1 lk. wide, course W. Ascend.	-200
40.00	Mark a Yew, 8 ins. diam., S 34 on E and S 33 1/2 S on W faces for 1/4 Sec. cor. from which A Fir, 8 ins. diam., bears N.38°E., 32 lks. dist., marked S 34 1/2 S B T. A Fir, 18 ins. diam., bears S.42°W., 68 lks. dist., marked S 34 1/2 S B T.	
52.00	Top of round knoll. Along N. slope of ridge.	+300
80.00	Marked a Fir, 10 ins. diam., T 31 S S 27 on NE, R 9 W S 34 on SE, S 33 on SW and S 28 on NW faces, with 1 notch on S and 3 notches on E. edges, for the corner of Secs. 27, 28, 33 and 34, from which	

33 \*per research  
8/30/2010  
DCSO, JC