

SUBDIVISIONS OF T. 31 S., R. 9 W.

CHAINS

N.0*04'W on Random line bet. Secs. 5 and 6.

40.00 Set temp. $\frac{1}{4}$ Sec. corner.

71.11 Intersect N. boundary of Township 40. lks. East of cor. of Secs. 5, 6, 31 and 32.

Thence I run

S.0*24'East on true line bet. Secs. 5 and 6.

.75 Top of ridge, course NE and SW.

1.75 Steep descent SE slope of mountain.

15.25 Creek 1 lk. wide, course E. -300

31.11 Marked a Fir, 18 ins. diam., S 5 $\frac{1}{4}$ S on E and S 6 $\frac{1}{4}$ S on W faces for the $\frac{1}{4}$ Sec. corner from which

A Fir, 16 ins. diam., bears N.78*E., 11 lks. dist., marked S 5 $\frac{1}{4}$ S B T.

A Fir, 18 ins. diam., bears N.32*W., 63 lks. dist., marked S 6 $\frac{1}{4}$ S B T.

Top of spur, course E. +200

39.76 Creek 1 lk. wide, course E. -300

44.15 Top of spur on line, course E. +100

50.00 Creek 8 lks. wide, course NE. -300

Steep ascent.

59.00 Top of spur on line, course NE. +300

71.11 To the corner of Secs. 5, 6, 7 and 8.

Land, mountainous.

Soil, rocky, 3rd rate.

Timber, Fir, Hemlock, Cedar, Yew, Laurel and Chinquapin.

Undergrowth, Fir, Hemlock, Cedar, Yew, Laurel, Chinquapin, Rhododendron, Balm, Vinemaple, Thimble and Salalberry.

Mountainous, heavily timbered or covered with dense undergrowth. 71.11 chains.

May 21st, 1901.