

SUBDIVISIONS OF T. 31 S., R. 9 W.

CHAINS

The closings not being satisfactory in the lines between Secs. 5 and 6, and 6 and 7, I remeasure the North boundary of Sec. 6.

Beginning at the established corner of Secs. 5, 6, 31 and 32 on N. boundary of township I run N.89\*43'W along old blazed lines.

- .50 Eden and Camas Valley trail, course NE and SW.
- 1.00 Steep descent NW slope of mountain.
- 31.72 A creek 3 lks. wide, course N.
- 40.30  $\frac{1}{4}$  Sec. cor. and witness standing.
- Ascend over small canyons and spurs, course NE.
- 76.25 Enter slide, course NE.
- 80.76 Leave slide, top of bluff, course NW and SE.
- 83.28 The township corner of Township 30 South, Ranges 9 and 10 West.

-800

+600

Land, mountainous.  
 Soil, rocky, 4th rate.  
 Timber, Fir, Hemlock, Cedar and Yew.  
 Undergrowth, Fir, Hemlock, Cedar, Yew, Rhododendron, Salal, Vinemaple and Huckleberry.  
 Dense undergrowth of same.  
 Mountainous, heavily timbered or covered with dense undergrowth. 83.28 chains.

May 21st, 1901.

General Description

The lands of this township are varied. The general features are rough and mountainous with very inferior soils, generally rocky. There are, however, a number of small valleys and benches of land capable of being cultivated.

It is fairly well timbered with Fir, Hemlock, Cedar,