

Subdivisions of Tp. 32 S., R 7 W.

CHAINS	
	East, on Random line between Sec. 3 and 10 Va.19*E
15.30	Creek 3 lks wide course N
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
50.50	Top of Spur course NE Descend.
79.97	Intersect 20 lks S of the corner to Sections 2, 3, 10 and 11. Thence I run S. 89*51' W. on true line between Secs. 3, and 10 Va. Same.
39.98	Marked A Fir, Tree 8 ins. in diam., for the $\frac{1}{4}$ Sec. Cor. marked $\frac{1}{4}$ S on N side from which: A Fir, 16 ins. diam., bears N.60*E., 9 lks. dist. marked $\frac{1}{4}$ S B T. A Fir, 10 ins. diam., bears S.10*E., 25 lks. dist. marked $\frac{1}{4}$ S B T.
79.97	To corner to secs. 3, 4, 9 and 10 Land mountainous heavily timbered. Soil clay and gravel 3rd rate. Timber chiefly Fir, Cedar, Pine, and Laurel. Undergrowth same.
	North on Random line between Secs. 3 and 4 Va.19*E Steep descent.
13.25	Deep Canyon and Creek 1 lk. course NE Begin ascent.
35.90	Trail course NE & SW
37.00	Top of Ridge course NE Begin descent.
40.00	Set temporary $\frac{1}{4}$ Sec. Cor.
75.00	Creek 6 lks wide course NE
82.16	Intersect N boundary of Township 63 lk E of the corner to Secs. 3, 4, 33 and 34 Viz; A Cedar post, 4 ins sq., firmly set in ground, marked T 31 S R. 7 W S 34 on NE