

Subdivisions of T 25 S. R. 5 $\frac{1}{2}$  E.

CHAINS

West on a true line, bet. secs. 5 and 8

Over mountainous land heavily timbered and with dense undergrowth.

Ascending from cor. E. slope of ridge.

30.00 Summit of ridge bears NE. and SW. Descend.

40.00 Set a hemlock post, 3 ft. long, 4 ins. sq. 2 ft. in ground, for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S 5 on N and 8 on S faces, from which,A hemlock, 6 ins. in dia., bears N.20\*E. 24 lks. dist. marked  $\frac{1}{4}$  S 5 B T.A fir, 10 ins. in dia., bears S.25\*E. 39 lks. dist., marked  $\frac{1}{4}$  S 8 B T.

40.26 Intersect W. bdy. of Tp. 17.34 chains N. of cor. of secs. 1 and 12.

Set a hemlock post, 3 ft. long, 4 ins. sq. 2 ft. in ground, for closing cor. of secs. 5 and 8, marked C C T 25 S R 5 $\frac{1}{2}$  E on E S 8 on S and S 5 on N faces with 1 groove on N and 5 on S sides, from which,A hemlock, 13 ins. in dia., bears N.15\*E. 31 lks. dist., marked T 25 S R 5 $\frac{1}{2}$  E S 5 B T.A hemlock, 6 ins. in dia., bears S.15\*E. 40 lks. dist., marked T 25 S R 5 $\frac{1}{2}$  E S 8 B T.

Land mountainous heavily timbered and with dense undergrowth.

Soil, volcanic ashes, 4th rate.

Timber hemlock and fir.

Undergrowth hemlock and fir.

Mountainous or heavily timbered land, 40.26 chains.

Sept. 30, 1902

## General Description

This fragment of a township constituting only tier and a half of section on the North is in the heart of the Cascade mountains and is consequently mountainous and broken.

The soil is of little fertility and is 4th rate.

Water abounds frequently in small lakes and ponds.

The mountains are covered with dense forests, fir, hemlock pine and larch for which the township is chiefly valuable.