

Subdivisions, T. 26 S., R. 1 E.

CHAINS	
	Ascend 685 ft. over broken E. slope.
43.20	Panther Creek Way Trail, bears S.15*E., and N.15*W.
53.90	Creek, 1 lk. wide, course N.80*E.
59.30	Same creek, course S.70*E.
79.70	The cor. of secs. 7, 8, 17 and 18.
	Land, mountainous.
	Soil, rocky loam, third rate.
	Timber, fir.
	Undergrowth, cinnamon bark and vine maple.
	West, on a true line bet. secs. 7 and 18.
	Ascend 20 ft. over E. slope, through timber and brush.
2.00	Spur, slopes N.20*E.
	Descend 730 ft. over broken W. slope.
19.40	Draw, course NW.
24.10	Timber Creek, 1 lk. wide, course N.
	Ascend 230 ft. over NE. slope.
34.70	Spur, slopes N.
	Descend 30 ft. over NW. slope.
36.90	Creek, 1 lk. wide, course N.30*E.
	Ascend 40 ft. over NE. slope.
40.00	Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap marked,
	$\begin{array}{r} S\ 7 \\ \frac{1}{4} \text{---} \\ S\ 18 \\ 1928 \end{array}$
	from which
	A hemlock, 10 ins. diam., bears S.20*E., 14 lks.
	Marked $\frac{1}{4}$ S 18 B T.
	A fir, 9 ins. diam., bears N.40*W., 45 lks. dist.
	Marked $\frac{1}{4}$ S 7 B T.
	Ascend 220 ft. over E. slope.
42.46	Cougar Creek Trail, bears S. and N.30*W.
50.30	Spur, slopes N.