

Township 26 South, Range 3 East.

CHAINS

General Description

Note: Through oversight no iron post was available when the cor. of secs. 27, 28, 33 and 34 was reached and native material, a stone of liberal proportions was substituted. To avoid a return to the field with the attendant delay and expense, this action subsequently received the approval of the District Cadastral Engineer.

(Signed) Otto L. Draper,

U. S. Transitman.

Portland, Oregon

March 15, 1931.