

Township 30 South, Range 3 East.
Resurvey of South Boundary.

CHAINS

S.89°34'W., bet. Secs. 5 and 32.

Over mountainous land, through heavy timber and medium undergrowth.

Desc. 675 ft. over W. slope to $\frac{1}{4}$ sec. cor.

36.55 Spring branch, 2 lks. wide, course SW.; continue desc.

39.73 Point 40.00 chs. in Westing from SE. cor. of Sec. 32.

Set an iron post, 3 ft. long, 1 in. dia., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor. of Sec. 32 only, with brass cap mkd.

$\frac{1}{4}$ S 32

1928

from which

A Hemlock, 10 ins. dia., bears N.29°E., 73 lks. dist., mkd. $\frac{1}{4}$ S 32 B T.

A Fir, 12 ins. dia., bears N.32°W., 60 lks. dist., mkd. $\frac{1}{4}$ S 32 B T.

40.12 The $\frac{1}{4}$ sec. cor. established for Secs. 5 and 32, which is a sandstone, 12x10x6 ins. loosely set, marked $\frac{1}{4}$ on N. face. In place of the stone

Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor. of Sec. 5 only, with brass cap mkd.

$\frac{1}{4}$ S 5
1928

from which

A Hemlock, (orig.) 28 ins. dia., bears S.1°W., 24 lks. dist., old blaze healed over, not opened.

A Hemlock, (new) 12 ins. dia., bears S.58°W., 35 lks. dist., mkd. $\frac{1}{4}$ S 5 B T.

A tree stump, 16 ins. dia., rotted nearly to the ground, bears N.23°W., 38 lks. dist., no visible marking, seems to be the original bearing tree.