

Subdivisions, T. 31 S., R. 2 E.

CHAINS	
66.50	A branch, 5 lks. wide, course East.
81.25	The cor. to secs. 1, 2, 11 and 12. Land, broken. Soil, 2nd rate. Timber, Fir and Pine. Undergrowth, Balm and Lilac. Heavily timbered. Dense undergrowth.
	81.25 chs. Sept. 23, 1891.
	From the cor. to secs. 2, 3, 34 and 35. I ran on South bdy. of Tp. N.0°02'W., on true line bet. secs. 34 and 35. Var.18°35'E. Through heavy timber.
13.00	A branch, 4 lks. wide, course SW. Ascend.
24.50	A spring, course E.
26.75	A branch, 3 lks. wide, course S.15°E.
29.00	A branch, 3 lks. wide, course SW.
40.00	About 400 ft. above sec. cor. marked a stone, in place 48x80x36 ins. for $\frac{1}{4}$ sec. cor. marked + in exact line pont, and $\frac{1}{4}$ S on West side, from which A Cedar, 12 ins. diam., bears S.40°W., 35 lks. marked $\frac{1}{4}$ S B T. A Cedar, 24 ins. diam., bears N.2°E., 63 lks. marked $\frac{1}{4}$ S B T.
41.00	A branch, 2 lks. wide, course SE.
52.00	Offset West 150 lks, to avoid bluff.
69.50	Offset East to line.
77.50	Summit of a ridge,
80.00	A point, about 1500 ft. above cor. of 34 and 35.

+ 1500