

County Surveyor's Record, Douglas County, Oregon 12029

15

HOMESTEAD ENTRY SURVEY NO. 143
 METES AND BOUNDS SURVEY OF JOSEPH HUTCHINSON, HOMESTEAD ENTRY,
 UMPQUA NATIONAL FOREST
 OREGON

CHAINS

BOUNDARIES OF H.E.S. NO. 143
LATITUDES, DEPARTURES AND CLOSING ERRORS

Line Designated	True Bearing	Dist.	Latitude		Departure	
			N. Chs.	S. Chs.	E. Chs.	W. Chs.
Cor. 1 - 2	N.0°30'E.	2.04	2.04		.02	
2 - 3	S.89°09'E.	11.96		.18	11.96	
3 - 4	N.4°57'E.	3.36	3.35		.29	
4 - 5	N.78°35'E.	5.32	1.05		5.21	
5 - 6	N.47°24'E.	3.78	2.56		2.78	
6 - 7	N.28°30'E.	10.43	9.17		4.98	
7 - 8	North	7.70	7.70			
8 - 9	East	3.68			3.68	
9 - 10	N.4°26'W.	3.84	3.83			.30
10 - 11	N.5°00'E.	8.40	8.37		.73	
11 - 12	N.27°04'E.	3.00	2.67		1.37	
12 - 13	N.38°03'W.	5.47	4.31			3.37
13 - 14	N.19°08'E.	2.74	2.59		.90	
14 - 15	S.59°00'E.	5.38		2.78	4.62	
15 - 16	N.29°50'E.	14.66	12.72		7.29	
16 - 17	N.15°53'E.	8.23	7.92		2.25	
17 - 18	N.7°25'E.	6.10	6.05		.79	
18 - 19	N.19°12'E.	2.54	2.40		.84	
19 - 20	S.70°07'E.	3.36		1.14	3.16	
20 - 21	S.6°55'E.	6.98		6.93	.84	
21 - 22	S.23°48'W.	12.89		11.79		5.20
22 - 23	S.66°12'E.	.23		.09	.21	
23 - 24	S.12°51'W.	5.51		5.37		1.23
24 - 25	S.24°09'W.	8.43		7.69		3.45
25 - 26	S.5°08'W.	12.01		11.96		1.07
26 - 27	S.8°23'W.	16.71		16.53		2.44
27 - 28	S.29°33'W.	16.83		14.64		8.30
28 - 29	S.59°30'W.	2.85		1.45		2.45
29 - 30	S.86°08'W.	12.79		.86		12.76
30 - 31	N.62°30'W.	7.68	3.54			6.81
31 - 1	N.76°11'W.	4.73	1.13			4.59
Totals -		219.63	81.40	81.41	51.92	51.97
Errors -				<u>81.40</u>		<u>51.92</u>
				.01		.05

Frank D. Maxwell
 Surveyor, Forest Service