

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines, T. 27 S., R. 3 W.

CHAINS

T 27 S R 3 W

S 6	S 5
S 7	S 8

1958

from which

A madrone, 6 ins. diam., bears N. $47\frac{1}{2}^{\circ}$ E., 22 lks. dist., mkd. T27S R3W S5 BT.

A madrone, 6 ins. diam., bears S. 30° E., 24 lks. dist., mkd. T27S R3W S8 BT.

A madrone, 6 ins. diam., bears S. 66° W., 13 lks. dist., mkd. T27S R3W S7 BT.

A madrone, 6 ins. diam., bears N. 36° W., 63 lks. dist., mkd. T27S R3W S6 BT.

From this point the $\frac{1}{4}$ sec. cor. of secs. 5 and 8, bears S. $89^{\circ} 38'$ E., 39.71 chs. dist., perpetuated with an iron pipe, $\frac{1}{2}$ in. diam., firmly set, 2 ins. above ground, at record bearing and distance from the two original bearing trees:

A fir, 25 ins. diam., bears N. 20° E., 4 lks. dist., with an opened blaze, no marks visible.

A fir, 25 ins. diam., bears S. 20° W., 4 lks. dist., bark scribed $\frac{1}{4}$ S5 BT CS.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, with brass cap mkd.

T 27 S R 3 W

$\frac{1}{4}$ S 5	S 8
-------------------	-----

1958

from which

A cedar, 9 ins. diam., bears N. $51\frac{1}{4}^{\circ}$ W., 54 lks. dist., mkd. $\frac{1}{4}$ S5 BT.

A fir, 8 ins. diam., bears S. 61° E., 32 lks. dist., mkd. $\frac{1}{4}$ S8 BT.

Deposit local corner material alongside iron post.

From this same point the corner of secs. 5, 6, 31, and 32, on the N. bdy. of the Tp., bears N. $0^{\circ} 12'$ E., 80.85 chs. dist., perpetuated with an iron post, $\frac{3}{4}$ in. diam., firmly set, 1 in. above ground, at record bearing and distance from the only remaining original bearing tree:

A white oak stump, 15 ins. diam., bears N. 23° W., 55 lks. dist., with illegible scribe marks on a partially healed blaze.

and locally established bearing trees:

A fir stump, 20 ins. diam., bears S. 32° W., 47 lks. dist.,

A white oak stump, 30 ins. diam., bears N. 45° W., $98\frac{1}{2}$ lks. dist., with scribe marks R3W S31 CS BT visible on an opened blaze.