

County Surveyor's Record, Douglas County, Oregon

1

T. 22 S., R. 10 W.

CHAINS

The following field notes describe the remonumentation of an original corner point, T. 22 S., R. 10 W., as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories Followed by Remonumentation of Corner Points, With New Accessories When Needed".

The remonumentation of the corner was requested by the Coos Bay District Manager for administrative purposes of the Bureau of Land Management.

(Remonumentation of a corner established in 1894 by Aurelius Todd and remonumented in 1919 by Charles M. Collier.)

The cor. of secs. 1 and 2 only, which is monumented with an iron post, 3 ft. long, 2 ins. diam., badly rusted, leaning and protruding 18 ins. above the ground, with brass cap marked

S 2	S 1
T 22 S R 10 W	
1919	

The bearing trees are gone.

At the corner point

Set an iron post, 30 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap marked

S 2	S 1
T 22 S R 10 W	
1963	

from which a new bearing tree

A sawed fir stump, 26 ins. diam., bears S. 51½° W., 39 lks. dist., marked T22S R10W S3 BT.

No other suitable bearing tree or bearing object available.

Deposit old iron post alongside new iron post as a memorial.