

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 5, T. 32 S., R. 5 W.

CHAINS	
	<p style="text-align: center;">C $\frac{1}{4}$ S 5 1962</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N. 2° E., 16 lks. dist. mkd. C $\frac{1}{4}$ S5 BT.</p> <p style="padding-left: 40px;">A fir, 13 ins. diam., bears S. 47° W., 37 lks. dist., mkd. C $\frac{1}{4}$ S5 BT.</p> <p>Descend 210 ft. over N. slope.</p>
47.50	Creek, 1 lk. wide, course N. 65° W.; asc. 30 ft. over SW. slope.
50.70	Spur, slopes N. 60° W.; desc. 115 ft. over N. slope.
56.00	Gully, drains N. 75° W.; desc. 80 ft. over NW. slope.
63.30	Spur, slopes N. 60° W.; desc. 65 ft. over N. slope.
65.10	Gully, drains N. 60° W.; asc. 30 ft. over SW. slope.
66.00	Spur, slopes W.; desc. 80 ft. over NW. slope.
75.60	Ravine, drains S. 50° W.; asc. 35 ft. over SE. slope.
77.00	The $\frac{1}{4}$ sec. cor. of sec. 5 only, on the N. bdy. of the Twp.
	<p>Land, mountainous. Soil, rocky clay. Timber, fir, white fir, hemlock, cedar and live oak, undergrowth, poison oak, salal, vine maple, arrowwood and manzanita.</p>
	<p>From the $\frac{1}{4}$ sec. cor. of secs. 4 and 5.</p> <p>N. 89° 53' W.; along the E. and W. center line of sec. 5.</p> <p>Ascend 285 ft. over SE. slope.</p>
16.00	Ridge, bears N. 10° E. and S. 20° W.; desc. 700 ft. over steep, rocky NW. slope, changing to N. slope.
37.98	The center $\frac{1}{4}$ sec. cor. of sec. 5.
	Descend 105 ft. along N. slope.
54.00	Spur, ridge, bears N. 80° W. and S. 70° E.; desc. 725 ft. over W. slope changing to NW. slope.
78.43	The $\frac{1}{4}$ sec. cor. of secs. 5 and 6.
	<p>Land, mountainous. Soil, rocky clay Timber, fir, white fir, hemlock and cedar; undergrowth, salal, poison oak, manzanita, live oak and vine maple.</p>
	<p>GENERAL DESCRIPTION</p> <p>Section 5 is located approximately seven miles south of Canyonville, Oregon. It lies on the west slopes of Buckhorn Mountain, elevation nearly 3,800 feet above sea level. There are no streams of any size, with all drainage in a southerly and westerly direction. Access into the section is limited to a dirt road extending from Fortune Branch, a small community</p>