

13624 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of Portion of Subdivisional Lines,
T. 31 S., R. 7 W.

| CHAINS | |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | manzanita, live oak, whitethorn, vine maple, young timber, vines, and ferns. |
| | From the cor. of secs. 2, 3, 34, and 35, on the S. bdy. of the Tp. |
| | N. 0° 05' E., bet. secs. 34 and 35. |
| | Descend 75 ft. over NE. slope, through heavy timber and thin undergrowth. |
| 0.10 | Dirt road, 15 lks. wide, bears N. 75° W. and S. 75° E. |
| 3.10 | Creek, 1 lk. wide, course E.; asc. 60 ft. over SE. slope. |
| 9.85 | Spur, slopes E.; desc. 60 ft. over NE. slope. |
| 16.55 | Creek, 2 lks. wide, course E.; asc. 60 ft. over SW. slope. |
| 21.25 | Dirt road, 15 lks. wide, course N. 25° W. and NE., on curve. |
| 21.50 | Spur, slopes SE.; desc. 25 ft. over NE. slope. |
| 24.85 | Draw, drains E.; asc. 50 ft. over SE. slope. |
| 28.15 | Top of ascent, slopes E.; desc. 110 ft. along broken E. slope. |
| 39.935 | Point for the $\frac{1}{4}$ sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner. |
| | Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. |
| | T 31 S R 7 W $\frac{1}{4}$ S 34 S 35 1964 |
| | from which |
| | A fir, 16 ins. diam., bears S. 14° E., 88 lks. dist., mkd. $\frac{1}{4}$ S35 BT. |
| | A fir, 17 ins. diam., bears S. 75 $\frac{1}{2}$ ° W., 77 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S34 BT. |
| | Descend 80 ft. along E. slope. |
| 50.40 | Spur, slopes NE.; desc. 165 ft. over N. slope. |
| 56.70 | Middle Creek Road, 15 lks. wide, bears N. 85° E. and S. 85° W. |
| 57.75 | Middle Creek, 25 lks. wide, course S. 85° W.; asc. 430 ft. over SE. slope, changing to S. slope. |
| 76.30 | Spur, slopes SW.; desc. 20 ft. over NW. slope. |
| 79.87 | The cor. of secs. 26, 27, 34, and 35, recorded and remonumented in 1961 by Howard W. Johnstone, Registered Land Surveyor No. 498, with an iron pipe, 1 in. diam., 6 ins. above ground, firmly set, from which the remains of the original bearing trees: |