

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion
of the Subdivisional Lines,
T. 31 S., R. 7 W., Willamette Meridian, Oregon

16552

CHAINS

40.74

Point for the 1/4 sec. cor. of secs. 10 and 11, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the 1/4 sec. cor. of secs. 10 and 11, erroneously reestablished by Chatters, in 1974, bears S. 0° 21' W., 0.653 chs. dist., set, marked and witnessed as described in the official record.

I remove the iron post, and destroy the marks on the bearing trees, and at the true corner point.

Reset the iron post, 28 ins. long, 2 1/4 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 7 W
1/4
S 10 | S 11
1979
1974

from which

A grand fir, 8 ins. diam., bears S. 47° E., 15 lks. dist., mkd. 1/4 S11 BT.

A cedar, 12 ins. diam., bears N. 34 1/2° W., 18 1/2 lks. dist., mkd. 1/4 S10 BT.

Descend 60 ft. over NE. slope.

42.15

Creek, 3 lks. wide, course N. 70° E.; asc. 265 ft. over SE. slope.

53.45

Spur, slopes NE.; desc. 475 ft. over NW. slope.

72.00

Creek, 2 lks. wide, course N. 30° E.; asc. 70 ft. over SE. slope.

79.50

Spur, slopes E.; desc. 40 ft. over NE. slope.

81.10

Ravine, drains N. 50° E.; desc. 80 ft. over NE. slope.

83.42

Point for the cor. of secs. 2, 3, 10, and 11, at proportionate distance; there is no remaining evidence of the original corner.

From this point, the cor. of secs. 2, 3, 10, and 11, erroneously reestablished by Chatters, in 1974, bears S. 1° 21' W., 0.341 chs. dist., set, marked, and witnessed as described in the official record.

I remove the iron post, and destroy the marks on the bearing trees, and at the true corner point

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 31 S R 7 W
S 3 | S 2
S 10 | S 11
1979
1974

from which