

# County Surveyor's Record, Douglas County, Oregon

16742

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

## CHAINS

with a down maple alongside, 16 ins. diam.,  
no marks remaining on decayed blaze.

A hemlock snag, 27 ins. diam., bears  
S. 59 1/4° W., 85 lks. dist., with burned  
blaze. Rescribed T20S R8W S20 BT on new  
blaze.

and new bearing trees

A sawed and burned fir stump, 48 ins. diam.,  
bears N. 25° E., 187 lks. dist., mkd. T20S  
R8W S16 BT.

A maple snag, 20 ins. diam., bears S. 79° E.,  
159 lks. dist., mkd. T20S R8W S21 BT.

A sawed and burned fir stump, 65 ins. diam.,  
bears N. 65° W., 79 lks. dist., mkd. T20S  
R8W S17 BT.

Set a 5 ft. steel fence post alongside the  
iron post.

---

The 1/4 sec. cor. of secs. 16 and 21, monumented with an  
iron post, 1 in. diam., firmly set, projecting 10 ins.  
above ground, with brass cap mkd.

1/4  $\frac{S\ 16}{S\ 21}$   
1954

from which the remains of the original bearing tree

A fir snag, 36 ins. diam., bears S. 70° E.,  
6 lks. dist., no marks remaining on burned  
blaze. Rescribed 1/4 S21 BT on new blaze.

and the remains of the bearing tree marked in 1954

A sawed fir stump, 38 ins. diam., bears  
N. 35° E., 36 lks. dist., no marks remaining  
on burned blaze. Rescribed 1/4 S16 BT on new  
blaze.

Set a 6 ft. steel fence post alongside the  
iron post.

---

(Rehabilitating a corner reestablished by  
Thomas A. Tillman, Joseph S. Gawron,  
Hans W. Thielsen, and Raymond M. Bicknell, in 1954)

---

The 1/4 sec. cor. of secs. 16 and 17, determined at record  
bearing and distance from the remains of the bearing  
trees marked in 1954

A sawed fir stump, 28 ins. diam., bears  
S. 54° E., 39 lks. dist., with scribe marks  
1/4 S16 BT visible on open and burned blaze.  
Rescribed 1/4 S16 BT on new blaze.

A sawed fir stump, 56 ins. diam., bears  
S. 49 1/2° W., 62 lks. dist., no marks remaining  
on decayed blaze.

At the corner point