

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of 16754
 a Portion of the Subdivisional Lines,
 T. 26 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

(Restoring the survey by Addison R. and Samuel C. Flint in 1881, the survey by William P. Heydon in 1896, and correcting a portion of the resurvey by Peter A. Peterson and Daniel L. Berry in 1971)

Beginning at the 1/4 sec. cor. of secs. 11 and 12, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.

1/4	
S 11	S 12
T 26 S	R 8 W
1971	

from which the remains of the bearing trees mkd. by Peterson and Berry

A root hole, bears N. 86° E., 27.0 lks. dist., with down fir alongside, 12 ins. diam., with healed blaze.

A sawed fir stump, 16 ins. diam., bears N. 49° W., 41 1/2 lks. dist., with scribe marks 1/4 S11 visible on partially healed blaze.

and new bearing trees

A fir, 6 ins. diam., bears N. 88° E., 7 1/2 lks. dist., mkd. 1/4 S12 BT.

A fir, 5 ins. diam., bears S. 28 3/4° W., 42 lks. dist., mkd. 1/4 S11 BT.

N. 0° 01' W., bet. secs. 11 and 12, marking and blazing the true line.

Descend 300 ft. over N. slope, through heavy timber and dense undergrowth.

20.95

Point for the N 1/16 sec. cor. of secs. 11 and 12.

From this point, the N 1/16 sec. cor. of secs. 11 and 12, erroneously established by Peterson and Berry in 1971, bears N. 25° 51' E., 0.25 chs. dist., monumented with an iron post, 2 1/2 ins. diam., firmly set, protruding 6 ins. above ground and mkd. as described in the field notes of the resurvey.

Move the iron post to the corner point and

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1 1/16	
S 11	S 12
1983	
1971	

from which new bearing trees

A hemlock, 6 ins. diam., bears N. 86 1/2° E., 12 1/2 lks. dist., mkd. N 1/16 S12 BT.