

County Surveyor's Record, Douglas County, Oregon

17377

T. 28 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

The following field notes are those of the dependent resurvey of a portion of the subdivisional lines, and the subdivision of section 27, Township 28 South, Range 4 West, Willamette Meridian, Oregon.

The history of surveys pertaining to this resurvey is as follows:

The subdivisional lines were surveyed by William H. Byars, U.S. Deputy Surveyor, in 1881, and a portion of the subdivisional lines was resurveyed by Irving Zirpel, Jr. and William W. Glenn, Cadastral Surveyors, in 1958.

The resurvey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1973, and the Special Instructions for Group No. 1068, Oregon, dated June 2, 1981.

The directions of the lines were determined by deflections from azimuths obtained by direct solar observations and refer to the true meridian.

Preliminary to the resurvey, the lines of the original survey were retraced and search was made for all corners and other calls of the record. Identified corners were re-monumented in their original positions. The retrace-ment data were thoroughly verified and only the true line field notes are given herein. Only those lines bounding or crossing public lands were blazed. All lines not forming a closure were measured twice.

The geographic position of the W 1/16 section corner of sections 22 and 27, as determined by a direct tie to United States Coast and Geodetic Survey triangulation station, "DODSON 1942," is as follows:

Latitude 43° 06' 47.0"N Longitude 123° 09' 42.0"W

The mean magnetic declination is 19° 30' E.

Dependent Resurvey of
a Portion of the Subdivisional Lines,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

(Restoring the survey by William H. Byars in 1881
and the resurvey
by Irving Zirpel, Jr. and William W. Glenn in 1958)

Beginning at the cor. of secs. 26, 27, 34, and 35, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 2 ins. above ground, with brass cap mkd.

T 28 S	R 4 W
S 27	S 26
S 34	S 35
1958	

from which the remains of three original bearing trees

A decayed madrone stump, size indeterminate, bears N. 40° E., 56 lks. dist.; no marks visible.

A root hole, bears S. 65° W., 58 lks. dist., with fragments of madrone wood alongside.