

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey,
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

17915

CHAINS									
16.50	Creek, 1 lks. wide, course S. 70° W.; asc. over S. slope.								
21.50	Spur, slopes S.; desc. over SW. slope.								
26.20	Creek, 2 lks. wide, course S. 45° E.; asc. over NE. slope.								
31.07	Point for the closing cor. of secs. 27 and 28, hereinafter described.								
	Ascend over NE. slope								
38.75	The cor. of secs. 33 and 34 only, monumented with an iron post, 2½ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.								
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 10px;">T 22 S</td> <td style="padding: 0 10px;">R 9 W</td> </tr> <tr> <td style="padding: 0 10px;"></td> <td style="padding: 0 10px; border-bottom: 1px solid black;">S 28</td> </tr> <tr> <td style="padding: 0 10px; border-right: 1px solid black;">S 33</td> <td style="padding: 0 10px;">S 34</td> </tr> <tr> <td colspan="2" style="text-align: center; padding: 0 10px;">1974</td> </tr> </table>	T 22 S	R 9 W		S 28	S 33	S 34	1974	
T 22 S	R 9 W								
	S 28								
S 33	S 34								
1974									
	from which the remains of the original bearing trees								
	A sawed fir stump, 50 ins. diam., bears S. 12° E., 95 lks. dist., with illegible scribe marks visible on open blaze. (Record, S. 15° E.)								
	A sawed fir stump, 50 ins. diam., bears S. 40° W., 115 lks. dist., no marks visible on open blaze.								
	No suitable trees available.								
	Land, mountainous. Soil, rocky clay loam. Timber, fir, cedar, hemlock, alder, and maple; undergrowth, vine maple, hazel, blackberry, salmonberry, fern, salal, poison oak, and Oregon grape.								
	From the cor. of secs. 22, 23, 26, and 27								
	N. 88° 05' W., bet. secs. 22 and 27.								
	Descend over NW. slope, through heavy timber and dense undergrowth.								
4.20	Ravine, drains N. 20° W.; desc. over NW. slope.								
12.70	Creek, 4 lks. wide, course N.; asc. over NE. slope,								
18.60	Spur, slopes N.; desc. over NW. slope.								
19.87	Point for the E 1/16 sec. cor. of secs. 22 and 27								
	From this point the E 1/16 sec. cor. of secs. 22 and 27, erroneously established by Wofford, Rogers, and Chatters, in 1973-79, bears N. 38° 11' E., 0.191 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. and witnessed as described in the official record.								
	Remove the iron post, destroy the marks on the bearing trees, and at the true corner point								