

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the
 Subdivisional Lines, T. 24 S., R. 4 W., **18021**
 Willamette Meridian, Oregon

CHAINS

From which

A fir, 7 ins. diam., bears N. 40° E., 37 lks. dist., mkd. S 1/16 S35 BT.

A fir, 9 ins. diam., bears N. 85 3/4° W., 42 lks. dist., mkd. S 1/16 S34 BT.

Descend over NW. slope.

39.76

Point for the 1/4 sec. cor. of secs. 34 and 35, at proportionate dist.; there is no remaining evidence of the original corner.

From this point, the 1/4 sec. cor. of secs. 34 and 35, erroneously reestablished by Akin, in 1972, bears S. 5° 18' E., 0.51 chs. dist., set, marked, and witnessed as described in the official record.

Remove the iron post, destroy the marks on the trees and at the true corner point

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 24 S R 4 W
 1/4
 S 34 | S 35
 1985
 1972

from which

An ash, 15 ins. diam., bears N. 61° E., 65 1/2 lks. dist., mkd. 1/4 S35 BT.

A fir, 29 ins. diam., bears N. 76° W., 51 lks. dist., mkd. 1/4 S34 BT.

Descend over NW. slope.

40.80

Creek, 2 lks. wide, course N. 70° W.; asc. over SW. slope.

44.00

Barbed wire fence, bears N. 70° W., and S. 70° E.

53.85

Spur, slopes W.; desc. over NW. slope.

59.64

Point for the N 1/16 sec. cor. of secs. 34 and 35.

From this point, the N 1/16 sec. cor. of secs. 34 and 35 erroneously established by Akin, in 1972, bears S. 8° 30' E., 0.30 chs. dist., set, marked and witnessed as described in the official record.

Remove the iron post, destroy the marks on the trees and at the true corner point

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16
 S 34 | S 35
 1985
 1972

from which