

County Surveyor's Record, Douglas County, Oregon

18490

Subdivision of Section 3,
T 25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>A fir, 10 ins. diam., bears N. 39° E., 20 lks. dist., mkd. CN 1/16 S3 BT.</p> <p>A fir, 5 ins. diam., bears N. 45° W., 12 lks. dist., mkd. X at breast height and BT at the base.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue over SW. slope.</p>
47.40	Top of ascent, slopes W.; desc. over NW. slope.
48.960	The ¼ sec. cor. of secs. 3 and 34, on the N. bdy. of the Tp.
	<p>From the ¼ sec. cor. of secs. 2 and 3.</p> <p>S. 89° 25' 00" W., on the E. and W. center line of sec. 3.</p> <p>Ascend over SE. slope, through heavy timber and dense undergrowth.</p>
3.90	Dirt road, 15 lks wide, bears NE. and SW.
13.15	Spur, slopes SW.; desc. over broken NW. slope.
19.810	Point for the center E 1/16 sec. cor. of sec. 3.
	<p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>E 1/16</p> <p>C S 3 C</p> <p>1987</p> </div> <p>from which</p> <p>A cedar, 8 ins. diam., bears N. 10° E., 24 lks. dist., mkd. CE 1/16 S3 BT.</p> <p>A hemlock, 20 ins. diam., bears S. 85° E., 12 lks. dist., mkd. CE 1/16 S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue over broken NW. slope.</p>
21.90	Ravine, drains N. 40° W.; continue to desc.
29.50	Ravine, drains S. 55° W.; asc. over SE. slope.
32.70	Spur, slopes SW.; desc. over NW. slope.
39.620	The center ¼ sec. cor. of sec. 3,
	Continue over broken NW. slope.
43.60	Creek, 12 lks. wide, course S. 80° W.,; asc. over SE. slope.
45.90	Spur, slopes S.; desc. over steep, broken NW. slope.
53.70	Creek, 6 lks. wide, course S. 30° W.; asc. over SE. slope.
60.410	Point for the center W 1/16 sec. cor. of sec. 3.
	<p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p>